




# ***AVOMETER*** ***Model EM 272***

---

## ***Operating*** ***Instructions***



# SPECIFICATION

---

## Ranges

A.C./D.C. Voltage	30mV, 100mV, 300mV, 1V, 3V, 10V, 30V, 100V, 300V and 1 000V f.s.d.
A.C./D.C. Current	3 $\mu$ A, 30 $\mu$ A, 300 $\mu$ A, 3mA, 30mA, 300mA, and 3A f.s.d.
Resistance	1 $\Omega$ —4k $\Omega$ , 0—40k $\Omega$ , 0—400k $\Omega$ , 0—4M $\Omega$ and 0—40M $\Omega$ . Mid-scale values 40 $\Omega$ , 400 $\Omega$ , 4k $\Omega$ , 40k $\Omega$ , and 400k $\Omega$ .
Decibels	—50dB to +60dB in 10dB steps (0 dB level at 0.778V on the 1V range corresponding to 1 mW into 600 $\Omega$ .)

## Accuracy

(20°C and 50Hz a.c.)

A.C./D.C. Voltage ranges	$\pm$ 2.5% of f.s.d. (all ranges above 30mV). $\pm$ 5% of f.s.d. (30mV range only). all up to approx. 1kHz on a.c.
A.C./D.C. Current Ranges	$\pm$ 2.5% of f.s.d. (all ranges).
Resistance	$\pm$ 5% at centre scale.

## Bandwidth

(relative to 50Hz)

A.C. Voltage Ranges	$\pm$ 5% up to 20kHz (all ranges up to 100V f.s.d.). $\pm$ 5% up to 5kHz (300 and 1 000V ranges).
---------------------	--

---

## SPECIFICATION

---

A.C. Current Ranges

$\pm 5\%$  to 20kHz (all ranges).

Measurement at low frequencies is only limited by the effect of needle flicker.

### AC/DC Input Characteristics

Voltage Ranges

Impedance 316k  $\Omega$ /V up to a maximum of 10M  $\Omega$ .

Current Ranges

Maximum voltage drop between 120mV and 600mV at instrument terminals (see page 7).

### Overload Protection

A.C. and D.C. Voltage Ranges

Prolonged overload could cause slight deterioration of accuracy.

260V r.m.s. on all ranges up to 10V f.s.d.

1,000V r.m.s. on 30V range and above.

A.C. and D.C. Current Ranges

Typically 10 times full scale deflection but not exceeding 10A. The possibility of accidental damage on these ranges is reduced by the provision of a separate socket for current measurements. All ranges fused at 3.15A.

### Temperature Effect

Operating Range

0 to 40°C.

Storage Range

-40°C to +70°C.

Temperature Co-efficient

Less than  $\pm 0.1\%/^{\circ}\text{C}$  on all ranges over 30mV.

### Mechanical Shock

Will withstand a shock up to 40g.

---

## SPECIFICATION

---

### Batteries

One 15V battery type B154 (IEC 10F15).

Typical life 1 000 hours.

One 1.5V cell type HP7 (IEC R6) for resistance measurements only.

Battery check facility provided.

### Dimensions

146 × 95 × 57mm (5.75 × 3.75 × 2.25 in.) approx.

### Weight

450 g (15½ oz) approx. with batteries.

### Fuse Link

3.15A (ceramic) 20 × 5 mm. 25413-280  
(IEC 127 Sh 1)

### WARNING

When measuring voltage on live circuits, make sure that the meter is **NOT** switched to a current (Amps) or resistance (Ohms) range. This mistake can cause injury to the operator.

## GENERAL DESCRIPTION

---

The AVO EM272 Electronic Multimeter is an inexpensive, pocket sized, multirange instrument, using a conventional meter movement with a solid state current amplifier to give a high input impedance, wide frequency response and low battery consumption.

The multimeter is extremely simple to use, with only two controls. A single range switch selects all the ranges and also provides a Battery Check position. The AC/DC Function switch is combined with the Ohms Set Zero control. No electrical Set Zero is required, but mechanical zero adjustment is provided.

Three sockets are provided for input connections. One is common, one is used for voltage inputs and the other for current or resistance measurements.

The instrument is housed in a rugged, shockproof moulded case.

### WARNING

THE INSTRUMENT WILL CONTINUE TO INDICATE AFTER THE FUSE HAS FAILED, BECAUSE A HIGH VALUE RESISTOR IS CONNECTED ACROSS THE FUSEHOLDER.

This is intentional and acts as a safeguard, preventing operators from wrongly assuming a circuit to be 'dead' when in fact it is 'live'.

The reading is not accurate. When the meter is connected to voltages between 30V and 1000V only half the true voltage will be indicated. Below 30 volts the indication will be rather less than half. Care should be exercised therefore, particularly when checking mains circuits above 200V a.c.

# OPERATION

---

## Preliminary

### (a) *Battery Check*

Before use, the Range Selector should be set to the Battery Check position ( $\text{+}$ ) to ensure that the 15V amplifier battery is serviceable. If the meter indication is below the minimum battery limit marked on the scaleplate, the battery (15V) should be replaced. (See Page 6).

### (b) *AC Measurements with DC Component*

If measuring a.c. voltage or current in a circuit also carrying d.c., a capacitor should be connected in series with the instrument to block the d.c. The value of blocking capacitor chosen will depend upon the frequency of a.c. to be measured, e.g. if plotting an audio frequency response curve, a  $0.5\mu\text{F}$  capacitor will limit errors to 5% on the one volt range at 20Hz. A larger capacity will improve accuracy in proportion.

## AC/DC Voltage Measurement

- (a) Set the Function switch to AC ( $\sim$ ) or DC ( $\text{---}$ ) as required.
- (b) Set the Range Selector to the appropriate range. If the value to be measured is unknown, set to the highest voltage range. (When the circuit to be measured is connected the range settings can be decreased until an adequate pointer deflection is obtained).
- (c) Connect the circuit to be measured across the input terminals, one lead to Common ( $\text{---}$ ) and the other to V. The measured value will be obtained from the combination of the indicated value and the range in use.

## AC/DC Current Measurement

- (a) Set the Function switch to AC ( $\sim$ ) or DC ( $\text{---}$ ) as required.
-

## OPERATION

---

- (b) Set the Range Selector to the appropriate range. If the value is unknown, set to the highest range and then decrease the Range settings until an adequate pointer deflection is obtained when the circuit to be measured is connected.
- (c) Connect the circuit to be measured in series with the input terminals, one connection to Common (—) and other to A/Ω. Care should be taken to ensure that the circuit under test is not live when making connections.  
The measured value will be obtained from the combination of the indicated value and the range in use.

NOTE: When the instrument is set for Current measurement great care should be taken to ensure that it is not connected across a voltage source.

---

### Decibel Measurements

- (a) Set the controls and make connections as for AC Voltage measurement.
- (b) Decibel values may then be read directly on the dB scale provided. (0 dB level is at 0.778V on the 1V range corresponding to 1mW into 600Ω). The voltage ranging is such that the dB ranges are in steps of 10 dB.

### Resistance Measurement

- (a) Set the Function switch to AC (∞)
- (b) Set the Range Selector switch to an appropriate resistance range.
- (c) Connect the test leads to the Common (—) and A/Ω input terminals.
- (d) Short together the test leads and adjust the Ohms potentiometer for meter full scale deflection (zero ohms). If it is impossible to obtain zero ohms setting, the 1.5V cell should be replaced. (See Page 6).

## OPERATION

---

- (e) Connect the test leads across the unknown resistor.
- (f) The resistance value will then be indicated on the meter and the measured value will be obtained from a combination of the indicated value and the range in use.

### **Battery Replacement**

Replacement of the battery is easily effected. Remove the two screws from the back cover and open the instrument to reveal the batteries. Ensure that new batteries are inserted in the correct polarity.

### **Fuse Link**

The 3,15 A ceramic fuse is contained in the fuse-holder on the lower half of the printed circuit board. Access to this and to the two spare fuses carried in a clip at the top of the instrument, is by removing the two securing screws and lifting off the back cover.

## TECHNICAL INFORMATION

---

### **Mechanical Zero Setting**

Although seldom necessary, if the pointer is not on the zero position, it may be set to zero using the slotted screw adjuster. The 15V battery should be removed while this adjustment is carried out. When the instrument is switched on again with the battery replaced, it may be found that the zero is slightly off-set either in the positive or negative direction. This is quite normal and may be ignored as the up-scale reading accuracy will not be affected. Any deterioration in the 1.5V battery used for resistance measurements will be apparent when setting the Ohms zero during resistance measurements.



## TECHNICAL INFORMATION

---

### Instrument Design Features

The construction is similar to that of a conventional multimeter except that a current amplifier is connected between the input ranging resistors and the movement. This achieves a full scale reading for an input current of  $3.162\mu\text{A}$  as opposed to the conventional requirement of about  $40\mu\text{A}$  for f.s.d.

The amplifier also serves as a half wave rectifying circuit to provide measurements for both a.c. and d.c. inputs. The AC/DC switch which is integral with the Ohms Set Zero control, simply changes the gain of the amplifier to provide a waveform correction for sine wave a.c. operation.


No built-in capacitor is provided to block d.c. voltages when the instrument is set for a.c. measurement. This allows the user to select the value of capacitor most suited to his requirements. This flexibility is particularly valuable at low frequencies where a very large capacitor could be


used to exploit the excellent low frequency performance of the instrument.

The input impedance of the instrument is  $316\text{k}\Omega/\text{V}$  up to the 30V range; above this, the input impedance remains at a constant  $10\text{M}\Omega$ . By-pass resistors switched into the 0.1V attenuator tapping are used for range switching on the voltage ranges above 30V.

For current measurements low resistance shunts provide a nominal 100mV drop to match the 100mV range of the instrument. Due to the finite resistance of the inter-connections within the instrument (typically  $0.16\Omega$ ) the terminal voltage when measuring high currents will be in excess of the basic 100mV required for measurement. In the worst case, the terminal voltage for current measurements may be taken as  $0.120\text{V} + (0.16 \times \text{Current in Amps})$  for full scale deflection. The multimeter is well protected against overloads, but prolonged overloads could slightly affect the accuracy.

# CIRCUIT DIAGRAM





NOTE :-

M1, IS ON MODULE 1 etc.

P.R. IS ON PRINTED RESISTOR.

The Trade Marks *AVO* and *AVOMETER* are the exclusive property of Avo Limited.

Thorn Measurement &  
Components Division

*A member of the Thorn Group*



Avo Limited  
Archcliffe Road  
Dover, Kent, CT17 9EN  
England

Tel Dover (STD 0304) 202620  
Telex 96283 AVOMEG G  
Cables AVOMEG G

Part No 6170-330 Edition 4

Printed in England MP/